

Date: 17. AUG. 2021

Urgent Field Safety Notice
Transition Coupling

For Attention of*: Customers in Holland, Norway, Sweden, Switzerland, UK.

Contact details of local representative (name, e-mail, telephone, address etc.) *
...

Urgent Field Safety Notice (FSN)
Transition Coupling
Risk addressed by FSN

1. Information on Affected Devices*	
1	1. Device Type(s)*
.	Transitions couplings supplied in Patient Lifting System – mounted in ceiling
1	2. Commercial name(s)
.	Molift
1	3. Unique Device Identifier(s) (UDI-DI)
.	5707995013217
1	4. Primary clinical purpose of device(s)*
.	Patient Lifting System intended for sitting and horizontal transfer as well as standing and gait training situations
1	5. Device Model/Catalogue/part number(s)*
.	Article number: 1109650
1	6. Software version
.	N/A
1	7. Affected serial or lot number range
.	416147
.	416148
.	416149
.	417241
.	417242
.	417243
.	417244
.	417245
.	417246
.	417247
.	417248
.	417249
.	417250
.	417251
.	417252
.	417253
.	417254
.	417255
.	417256
.	417257
.	417258
.	417259
.	417260
.	417261
.	418671
.	418672

418673
418674
418675
418676
418677
418678
418679
418680
418681
418682
418683
418684
419248
419249
419250
419251
419252
419253
419254
419255
419256
419257
419258
419259
419260
419261
419262
419263
419264
419265
419266
419267
419268
419269
419270
419271
419272
419273
419274
421583
421584
421585
421586
421587
421588



421589
421590
421591
421592
421593
421594
421595
421596
421597
421598
421599
421600
421601
421602
421603
421604
421605
421606
421607
421608
421609
421610
421611
421612
421613
421614
421615
421616
421617
424579
424580
424581
424582
424583
424584
424585
424586
424587
424588
1 8. Associated devices
. N/A

2 Reason for Field Safety Corrective Action (FSCA)*

2	1. Description of the product problem*
.	It comes clear that when installing the patient lifting system the transition coupling may not lock as intended.
2	2. Hazard giving rise to the FSCA*
.	If the patient lifting system is used and the transitions coupling is not locked as intended, there is a potential risk that the hoist system can be detached from the rails and the motor can fall down.
2	3. Probability of problem arising
.	It may happen in limited cases.
2	4. Predicted risk to patient/users
.	If the detachment happen when lifting a patient, the patient might get injury due to the fall.
2	5. Further information to help characterise the problem
.	N/A
2	6. Background on Issue
.	Root cause is due to manufacturing site that by assembly has added too much loctite material.
2	7. Other information relevant to FSCA
.	Rework instruction for installers has been developed and are forwarded to relevant customers.

	3. Type of Action to mitigate the risk*	
3.	1. Action To Be Taken by the User*	
	<input type="checkbox"/> Identify Device <input type="checkbox"/> Quarantine Device <input type="checkbox"/> Return Device <input type="checkbox"/> Destroy Device <input checked="" type="checkbox"/> On-site device modification/inspection <input type="checkbox"/> Follow patient management recommendations <input type="checkbox"/> Take note of amendment/reinforcement of Instructions For Use (IFU) <input type="checkbox"/> Other <input type="checkbox"/> None Re-Work Instruction has been developed and the steps should be followed in order to eliminate the risk.	
3.	2. By when should the action be completed?	Before putting the system into service
3.	3. Particular considerations for:	
	Is follow-up of patients or review of patients' previous results recommended?	
	The system is normally checked at installation, where the issue will arise.	
3.	4. Is customer Reply Required? * (If yes, form attached specifying deadline for return)	Yes

3.	5. Action Being Taken by the Manufacturer <input type="checkbox"/> Product Removal <input type="checkbox"/> On-site device modification/inspection <input type="checkbox"/> Software upgrade <input checked="" type="checkbox"/> IFU or labelling change <input type="checkbox"/> Other <input type="checkbox"/> None Corrective Action has been forwarded to relevant customers	
3	6. By when should the action be completed?	Before putting the system into service
3.	7. Is the FSN required to be communicated to the patient /lay user?	No
3	8. If yes, has manufacturer provided additional information suitable for the patient/lay user in a patient/lay or non-professional user information letter/sheet?	

4. General Information*	
4.	1. FSN Type* New
4.	2. For updated FSN, reference number and date of previous FSN N/A
4.	3. For Updated FSN, key new information as follows: N/A
4.	4. Further advice or information already expected in follow-up FSN? * No
4	5. If follow-up FSN expected, what is the further advice expected to relate to: N/A
4	6. Anticipated timescale for follow-up FSN N/A
4.	7. Manufacturer information (For contact details of local representative refer to page 1 of this FSN)
	a. Company Name
	b. Address
	c. Website address
4.	8. The Competent (Regulatory) Authority of your country has been informed about this communication to customers. *
4.	9. List of attachments/appendices: Potential affected serial numbers, countries of customers and delivered amount
4.	10. Name/Signature 
	

Transmission of this Field Safety Notice	
	<p>This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred. (As appropriate)</p> <p>Please transfer this notice to other organisations on which this action has an impact. (As appropriate)</p> <p>Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.</p> <p>Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback.*</p>

Note: Fields indicated by * are considered necessary for all FSNs. Others are optional.